Form 9-331 Dec. 1973

Form A	pproved		
Budget	Bureau	No	42-P1424

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE	eau No. 42-R1424
GEOLOGICAL SURVEY	LC-032650 (b) 6. IF INDIAN, ALLOTTEE OR T	RIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME	
1 611	8. FARM OR LEASE NAME A. B. Coates C	
well well other	9. WELL NO.	
2. NAME OF OPERATOR	7	:
Getty Oil Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME	
P. O. Box 730, Hobbs, NM 88240	Justis Montoya 11. SEC., T., R., M., OR BLK. A	ND SUBVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA	
AT SURFACE: 1980' FNL & 1980' FEL	Sec. 24, T-25-S 12. COUNTY OR PARISH 13.	
AT TOP PROD. INTERVAL:	• - · · · · · · · · · · · · · · · · · ·	ew Mexico
AT TOTAL DEPTH:	14. API NO.	- HERIE
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		· -
REPORT, ON OTHER DATA	15. ELEVATIONS (SHOW DF,	KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3079	
TEST WATER SHUT-OFF		
FRACTURE TREAT SHOOT OR ACIDIZE T	The second secon	
REPAIR WELL	(NOTE: Report results of multiple of	completion or zone
PULL OR ALTER CASING MULTIPLE COMPLETE MULTIPLE COMPLETE	change on Form 9-330.)	completion of Zone
CHANGE ZONES		
ABANDON*		
(other) Additionally perforate & stimulate	e .	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent.)	e all pertinent details, and give rectionally drilled, give subsurfac t to this work.)*	pertinent dates, e locations and
1. Rig up pulling unit and pull rods a	and numn	
Install BOP and pull tubing.	and pamp.	
3. Set retrievable BP @ 6675'.		•
4. Test BP to 1000 psi. 5. Selectively perforate upper Montage		
berrotate abbet woutons	a from 6610-6642'.	2.2 7 3
6. Acidize perfs., 6610-42', with 3000 c7. Swab test.	gallons 15% acid.	** **
8. Retrieve BP.		
9. Run tubing, pump, and rods and place	ce well back on pro	nduction
-	. P10	sauceron.
		• 1
Subsurface Safety Valve: Manu. and Type	Set @	
18. I hereby certify that the foregoing is true and correct		•
SIGNED SIGNED TITLE Area Supt.	DATENovember	1978
(This space for Federal or State offic		U
APPROVED BY TITLE	PAROPRO	12
CONDITIONS OF APPROVAL, IF ANY:	NOV 6 1978	GINEER
*See Instructions on Reverse Si	NOV 6 ACTING DISTRICTED	VOII.