

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032650 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

JUSTIS MC KEE UNIT

9. WELL NO.

117

10. FIELD AND POOL, OR WILDCAT
JUSTIS ELLENBURGER &

JUSTIS MC KEE

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

24-25S-37E

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

GETTY OIL COMPANY

3. ADDRESS OF OPERATOR

P.O. BOX 249, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

960' FEL & 2,280' FNL of Section 24, T-25-S, R-37-E

14. PERMIT NO.

--

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,082' (DF)

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

To old Mc KEE ZONE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well is completed as a dual oil well in the Justis Ellenburger (7,764'-82') and Justis Mc Kee (7,304'-20') Zones. The Justis Mc Kee Waterflood Unit was abandoned effective July 1, 1971.

It is proposed to abandon the Mc Kee Zone and complete the well as a conventional single in the Ellenburger Zone. The Mc Kee perforations will be squeezed, cemented and tested to 1,000 psi. Proposed procedure:

1. Pull Mc Kee tubing
2. Pull Ellenburger Tubing
3. Go in hole with packer and ret. B.P.
4. Bracket the Mc Kee Zone and squeeze off the Mc Kee Perfs. 7,304'-20'
5. Wait on cement for 24 hours
6. Go in hole and drill out cement across the Mc Kee Zone
7. Pressure test squeeze to 1,000 PSI
8. Retrieve B.P. and complete well as per attached sketch.

18. I hereby certify that the foregoing is true and correct

SIGNED

C. L. Wade

(This space for Federal or State office use)

TITLE AREA SUPERINTENDENT

DATE September 3, 1971

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

847-485

RECEIVED

SEP 1 1971

U.S. DEPARTMENT OF COMMERCE
BUREAU OF MINING

GETTY OIL COMPANY
A. B. COATES "C" NO. 17 (JUST MC KEE WELL NO. 117)
JUSTIS FIELD
LEA COUNTY, NEW MEXICO
RECOMPLETION SKETCH
JULY 7, 1971

