

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Form Approved
Budget Bureau No. 42 R1424
5. LEASE DESIGNATION AND SERIAL NO.

LC 032650 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Cetty Oil Company</u>	8. FARM OR LEASE NAME <u>A. B. Coates "D"</u>
3. ADDRESS OF OPERATOR <u>P. O. Box 247, Hobbs, New Mexico</u>	9. WELL NO. <u>1</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>660' TSL, 1980' FWL, Sec. 24</u>	10. FIELD AND POOL OR WILDCAT <u>Langlie Mattix</u>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>24-25S-37E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3008' THP</u>	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>N. Mex.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Tagged up to P & A. Pull d 2-3/8" tubing, removed bull plug and perforated nipple. Re-ran tubing and laid a 40 sack cement plug 2926-2506'. Tagged top of cement plug at 2760'. Displaced hole with 10.3# brine mud. Laid 25 sack cement plug from 833' back to 619'. Laid 8 sack cement plug in 6-5/8" casing from 50' back to surface, and 10 sack cement plug in 6-5/8" - 9-5/8" annulus from 50' back to surface.

Installed dry hole marker and cleaned location. Ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed By TITLE Area Supt. DATE 5-12-72

(This space for Federal or State office use)

APPROVED BY A. P. WED TITLE Area Supt.

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SEP 2
RECEIVED
S. H. ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.