

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-11749</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>SOUTH JUSTIS UNIT "F"</b>
8. Well No. <b>19</b>
9. Pool name or Wildcat <b>JUSTIS BLBRY-TUBB-DKRD</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <b>ARCO Permian</b>	
3. Address of Operator <b>P.O. BOX 1610, MIDLAND, TX 79702</b>	
4. Well Location Unit Letter <b>C</b> : <b>660</b> Feet From The <b>NORTH</b> Line and <b>1980</b> Feet From The <b>WEST</b> Line Section <b>24</b> Township <b>25S</b> Range <b>37E</b> NMPM <b>LEA</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3078 GR</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **ADD B-T-D PERFS & TREAT** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-25-94.RUPU. POH W/CA. CO JUNK TO 6070 PBD. ACIDIZED B-T-D PERFS 5683-6043 W/ 4000 GALS. ISOLATE HOLES IN CASING F/3228-3353. SQZ'D W/ 300 SX "C". SQZ'D HOLES 3138-3200 W/ 220 SX "C". WOC. DO CMT F/2853-3433. PRESS TEST SQZ TO 300#. PERF B-T-D F/ 5010-5613. ACIDIZED W/ 2000 GALS. FRAC'D W/ 78,000 GALS CARRYING 226,000# SD. CO TO 6070 PBD. RIH W/CA:2 3/8 TBG,RODS & PUMP TO 5028. RDPV 12-15-94.

CURRENT PRODUCING INTERVAL 5010-6043.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W Gosnell TITLE AGENT DATE 12-20-94  
TYPE OR PRINT NAME Ken W. Gosnell TELEPHONE NO. 915 688-5672

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

DEC 22 1994

HOBBS  
OFFICE