Submit 3 Copies to Appropriate District Office

> Type or Well: WELL

2. Name of Operator

3. Address of Operator

Well Location

11.

Unit Letter _

Section

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

work) SEE RULE 1103.

CONDITIONS OF APPROVAL, IF ANY:

X

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

OTHER

79702

25S

PLUG AND ABANDON

CHANGE PLANS

North

3082.7 GR

Line and

37E

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

Range

SUNDRY NOTICES AND REPORTS ON WELLS

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Texas

Township

660 Feet From The

P.O. Drawer DD, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

ARCO OIL AND GAS COMPANY

Box 1610, Midland,

OIL CONSERVATION DIVISION

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-11753 5. Indicate Type of Lease FEE X STATE State Oil & Gas Lease No. (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name Wimberly WN 8. Well No. 9. Pool name or Wildcat Jutis Fusselman 990 West Feet From The Line Lea **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: **ALTERING CASING** REMEDIAL WORK

PLUG AND ABANDONMEN

OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

Propose to temporarily abandon as follows:

- 1. POH w/CA
- 2. Set CIBP at 6500

NOTICE OF INTENTION TO:

X

Circ hole W/TFW 3.

(This space for State Use) Paul Geol	Estitz Ogist	DATE -
TYPEOR PRINT NAME Ken W. Gosnell	915/688-56	72 TELEPHONE NO.
I hereby certify that the information above is true and complete SIGNATURE Ken W Los LU	e to the best of my knowledge and belief. TITLE Engr. Tech.	DATE 8/20/90