

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0766

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carlson "A"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT
JUSTIS (Blinebry)

(Tubb-Drinkard)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 25, T25S, R37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3066 DE

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pulled Blinebry and Tubb-Drinkard tubing. Plugged Tubb-Drinkard perforations with form-gel and tested. Plugged Blinebry perforations with form-gel and tested.
2. Milled over Model D packer at 5325'. Drilled bridge plug at 6010'. Drilled cement retainer at 6900' and drilled cement to 7033'.
3. Perforated casing at 7010 with 4 single-plant jets. Set retainer at 6826, squeezed perforations with 100 sacks class "C" cement.
4. Drilled retainer and cement to 7002 IPTD. Perf. Russelman 6984-6998. Acidized with 1250 gallons 15% NE acid.
5. Swabbed 85 to 98 per cent water. Squeezed formation with 100 sack diesel oil cement.
6. Swabbed well at rate of 1 1/2 BPH, 50% water. Acidized with 500 gallons 15% NE acid.
7. Swabbed at rate of 23 BPH, 97% water. Ran cement retainer to 6854, squeezed Russelman perms 6984-6998 with 100 sack neat cement.
8. Perforated additional Tubb-Drinkard section from 5715 to 5820. Acidized w/1500 gal 15% acid & fractured w/20,000 gal gelled brine & 23,500 sand.
9. Perforated additional Blinebry section from 5182 to 5603. Acidized w/1250 gal 15% acid & fractured w/71,500 gal gelled brine and 107,250 sand.
10. Set Baker Model FA packer at 5651' to separate zones.
11. Returned well to producing status.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

3/11/66

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.