

OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-11478
7. Unit Agreement Name
8. Farm or Lease Name State "Y"
9. Well No. 6
10. Field and Pool, or Wildcat Justis Montoya
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐

2. Name of Operator  
Atlantic Richfield Company

3. Address of Operator  
P. O. Box 1710, Hobbs, New Mexico 88240

4. Location of Well  
UNIT LETTER H 1650 FEET FROM THE North LINE AND 660 FEET FROM  
THE East LINE, SECTION 25 TOWNSHIP 25S RANGE 37E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)  
3065.5' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to treat Montoya perms 6915-6974' to stimulate production in the following manner:

Run treating pkr to approx 6900' and treat perms 6915-6974' w/1000 gal 15% HCL LSTNE acid.  
Swab back acid load. Run completion assembly back in well and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief,

SIGNED H. J. Bernard TITLE Dist. Drlg. Supv. DATE 9/3/74

Orls. Signed by Joe D. Ramey TITLE Dist. Supv. DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: