

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-11478	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
1. Name of Operator ARCO Oil and Gas Company		8. Farm or Lease Name State "Y"
3. Address of Operator P.O. Box 1610, Midland, Texas 79702		9. Well No. 8
4. Location of Well UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>25S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Justis Fusselman
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Return Fusselman to Production</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1709.

- 4-18-88. RUPU. Press test csg to 500#. Drill out CIBP at 5000'. CO to 6876. Re-perf'd Fusselman f/6725-6863. Acidize perms 6720-6863 w/10,000 gals. Swab load. RIH w/tbg. RD PU. 4-25-88.
- 5-4-88. Began pumping w/submersible pump.
- 5-5-88. In 21 hrs pmpd 129 BO, 784 BW, 102 MC FG.
- 5-11-88. In 24 hrs pmpd 232 BO, 1230 BW, 142 MCFG.
- 5-17-88. POH w/rental ESP & run permanent ESP.
- 6-19-88. In 24 hrs pmpd 128 BO, 1047 BW, 91 MCFG.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kenneth Gosnell TITLE Engr. Tech. 915-688-5672 DATE 6-27-88

ORIGINAL SIGNED BY JERRY SEXTON
PROVED BY DISTRICT 1 SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: