

Sketch for Dual
Completion Application

Carlson B25 No. 3 ..
☐ Existing open perforations
☒ old squeezed perforations

D.V. Tool on
7" csg @ 833'
with 230 5x cmt.

13 3/8" H-40 48" @ 845'
w/ 650 5x (cmt'd to surface)

Tubb
5640'

2 7/8" N-80 EWE
tubing for
Abo production

Driskard
5890'

Abo
6138'

Tubing conveyed
perforation assembly
Gun

5663
5664
5704
5714
5731
5742

5900
5905
5906
5910
5920
5930
5936
5942

Model "XL" on-off tool with 1.56" "F"
profile cut.

Guiberson Uni-VI pkr @ 6135'

6155' sqzd
6162' sqzd

6182
Frac w/
50x10 sd-oil,
6222 sqzd
☐ 6182 Acid w/1000 gallons
6186

PBD 6215'

CIBP @ 6250' capped w/ 35' cmt via bailer

6270' Tested water, sqzd.
6290'
6392' Tested dry, sqzd.
6404'

Junk
Lokset pkr @ 6444'

Fusselman SN @ 6473'

Fusselman
6756'

Junk RBP @ 6544'
Mod "b" pkr @ 6550'

7" 23" J-55 + N-80 @ 6652'

Junk Temperature
Logging Tool below
Mod "b" pkr

6 1/4" Open Hole

TD 6800' H-82 / ..