

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN T
(Other instru
verse side)ATE*
reForm approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. LL-032579(a)
2. NAME OF OPERATOR Westates Petroleum Company	6. INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 88, Jal, New Mexico	7. UNIT AGREEMENT NAME PR. Lease
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' from S. & 330' from E. line Sec. 26, 258, 37E. NE 1/4 SE 1/4 Sec. 26	8. FARM OR LEASE NAME Carlson B 26
14. PERMIT NO.	9. WELL NO. 5
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT Antia Hline, Tubb Drk.
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, 258, 37E.
	12. COUNTY OR PARISH Lea
	13. STATE N. Mex.

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7" casing 23' at 6249'.

Plugged lower Tubb Drk. perfs. at 5850'-5930'. Set Baker cast iron plug at 5835'. Cap with 11' cement. Top of cement 5824'. Shot nine new perfs. in Hlinebry zone. One 1/2" jet shot per int. @5218'-5243'-5259'-5302'-5325'-5340'-5347'-5348'-5380'. Acidise with 3000 gal. Super X 28% 3000 gal. 3% NE acid. Swab well. Test tubing in hole. Set Baker back set packer @5662'. P.S.A. @5629'. Run rods, put well on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED W. F. StullTITLE Prod. Supt.DATE 5-6-68

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE

MAY 9 1968

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 5: Proposals to abandon a well and subsequent reports of such abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid content not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing; and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1967 O-486229

507-651