#### NEW MEXICO OIL CONSERVATION COMMISSION

Santa, Fe, New Mexico

### MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below: NOTICE OF INTENTION TO TEST CASING NOTICE OF INTENTION TO SHOOT OR SHUT-OFF X CHEMICALLY TREAT WELL NOTICE OF INTENTION TO PULL OR NOTICE OF INTENTION TO CHANGE PLANS OTHERWISE ALTER CASING NOTICE OF INTENTION TO REPAIR WELL NOTICE OF INTENTION TO PLUG WELL NOTICE OF INTENTION TO DEEPEN WELL Midland, Texas May 20, 1938 OIL CONSERVATION COMMISSION. Santa Fe, New Mexico. Gentlemen: Following is a notice of intention to do certain work as described below at the Culbertson & Irwin, Inc. Alston .....Well No. Company or Operator 37-E, N. M. P. M., Langlie Field, of Sec. Lea ......County. FULL DETAILS OF PROPOSED PLAN OF WORK FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION Set 5-3/16" casing at 3190' and will cement, by Halliburton 2 stage job, with 350 sacks cement, upper stage being at 1125. HOBBS OFFICE CULBERTSON & IRWIN, MAY 2 4 1938 Approved except as follows: Treasurer Position Send communications regarding well to Name Culbertson & Irwh, Inc. OIL CONSERVATION COMMISSION

Address Box 1071

& Gas Inspector


Midland, Texas

## 

The state of the s

# 

# 



> and the second of the second of the second

 $\label{eq:constraints} g_{\rm const} = - \frac{1}{2} \left( 2 \pi \Omega_{\rm co} + 9 \Omega_{\rm cos} \right) + \left( \frac{1}{2} \left( 1 + \frac{1}{2} 2 \Omega_{\rm cos} \right) + \frac{1}{2} \left( 1 + \frac{1}{2} \Omega_{\rm cos} \right) \right) + \left( \frac{1}{2} \left( 1 + \frac{1}{2} \Omega_{\rm cos} \right) + \frac{1}{2} \Omega_{\rm cos} \right) + \left( \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} \right) + \left( \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} \right) + \left( \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} \right) + \left( \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2} \Omega_{\rm cos} \right) + \left( \frac{1}{2} \Omega_{\rm cos} + \frac{1}{2}$