

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI  
(Other instruction  
verse side)ATE  
& reForm approved.  
Budget Bureau No. 42-R1424.  
LEASE DESIGNATION AND SERIAL NO.

LC 034117(a)

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P & A	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Atlantic Richfield Company	8. FARM OR LEASE NAME Ruby S. Crosby "A"
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, N.M. 88201	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  2310' FSL & 330' FWL	10. FIELD AND POOL, OR WILDCAT Jalmat-Yates
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3022' GR
	12. COUNTY OR PARISH Log
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well has been plugged & abandoned in the following manner:

Spotted 30 sk Class "A" cement plug 2358-2508'. Perforated 7" casing @ 1325'. Circulated 9-5/8" x 7" annulus & cemented w/100 sx cement to 1225'. Wc 12 hrs. Perforated 7" casing @ 50'. Circulated 9-5/8" x 7" annulus w/30 sx Class "A" cement. Erected dry hole marker. Well P & A 4/28/71. 9#/gal gel mud was left between all cement plugs. 13" and 9-5/8" casing strings remain intact. Erected dry hole marker. 7" casing from 0-50' left full of cement.

Your office will be notified by letter when location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED A. D. Litcher TITLE Dist. Drlg. Supervisor DATE 5/5/71

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

AUG 11 1971

\*See Instructions on Reverse Side

J. L. GORDON  
ACTING DISTRICT ENGINEER

RECEIVED

AUG 17 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.