

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name EXXON C.T. Bates
2. Name of Operator William H. Brininstool D.B.A. XL TRANSPORTATION CO.	8. Well No. 1
3. Address of Operator P.O. DRAWER A JAL, N.M. 88252	9. Pool name or Wildcat JALMAT Y-SR-Q
4. Well Location Unit Letter C : 920 Feet From The NORTH Line and 2170 Feet From The West Line Section 29 Township 25S Range 37E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3034' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perfs. 2474'-2994'

1. Set 8 7/8 CIBP @ 2425' with 6sx. cmt. on top. (20ft.)
Circ. Hole with 9.5 mud Laden Fluid.

2. Spot 30sx. cmt. @ 555'-455'.

3. Spot 10sx. cmt. @ 30' - SURFACE.

Cut off Well Head And INSTALL DRY Hole MARKER.

RECEIVED
OIL CONSERVATION DIVISION
SANTA FE, NEW MEXICO
JUL 26 1991

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger D. Brooks TITLE _____ DATE 7-26-91

TYPE OR PRINT NAME Roger D. Brooks TELEPHONE NO. 915-362-4324

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JUL 26 1991

CONDITIONS OF APPROVAL, IF ANY: