

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
J.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. NMJ-584
7. Unit Agreement Name
8. Farm or Lease Name JENKINS
9. Well No. 2
10. Field and Pool, or Wildcat Jalmat Yates
12. County

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER- **Plugged and Abandoned**

Name of Operator
TEXAS PACIFIC OIL CO., INC.

Address of Operator
P. O. Box 1069 - Hobbs, New Mexico 88240

Location of Well
UNIT LETTER **K**, **1980** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **29** TOWNSHIP **25-S** RANGE **37-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3021' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PLUG OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Moved in & rigged up. Pulled rods and tubing (91 jts. 2-3/8" 4.7# 8rd. J-55 EUE)
2. Ran tubing w/CIBP @ 2625'.
3. Displaced well fluids w/mud laden fluid and spotted 15 sks. cement.
4. Pulled tubing and spotted 10 sks. cement at surface.
5. Cut off well head and capped w/cement.
6. Set dry hole marker, cut dead men and cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by
Sheldon Ward

ED _____ TITLE **Area Superintendent** DATE **7-15-71**

OVER BY **Nathan E. Pegg** TITLE **OIL & GAS INSPECTOR** DATE **DEC 7 1971**

DITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 16 1971

OIL CONSERVATION COMM.
HOBBS, N. M.