

Form 9-331a
(March 1942)

HOBBS

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. 054667
032510 (b)
Unit GregoryRECEIVED
JUL 26 1954SUNDRY NOTICES AND REPORTS ON WELLS
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Gregory July 23, 19 54

Well No. 1 is located 330 ft. from SW line and 2310 ft. from E line of sec. 33

SW SW SE 25S 37E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Langlie-Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to drill a well at the above location with rotary tools to a total depth of approximately 3600'. Casing Program: 300' of 8-5/8" 24# casing using 200 sacks of cement, we propose to set 2480' of 15.5# 5-1/2" pipe with 100 sacks of cement on first stage and 100 sacks of cement on 2nd stage.

Expected Formations: Yates 2490'
Queen 3000'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. OLSENAddress Drawer 'Z'Jal, New MexicoBy *Johnnie French*Title Superintendent