

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Dabbs
8. Well No. 1
9. Pool name or Wildcat Jalmat (Gas)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3005 G.L.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> OAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Doyle Hartman
3. Address of Operator P. O. Box 10426, Midland, Texas 79702	4. Well Location Unit Letter <u>M</u> : <u>990</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>34</u> Township <u>25-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Estimated starting date 9-8-89

1. Rig up pulling unit and install BOP.
2. Pull 2-3/8" tubing and Guiberson KV 30P Packer.
3. GIH Tbg & Halliburton EZ drill squeeze packer.
4. Circulate hole with 2% KCL (+100 bbls).
5. Set packer at 2440'.
6. Squeeze open hole interval (2546'-2852') with 100 sacks of API Class-C cement with 2% CaCl additive.
7. Release packer and POOH with tbg.
8. Evaluate

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Peggie Stacy TITLE Administrative Assistant DATE 9-8-89
TYPE OR PRINT NAME Peggie Stacy TELEPHONE NO 915/684-4011

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 11 1989

RECEIVED

SEP 11 1989

OCD
HOBBS OFFICE