



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
HOBBS DISTRICT OFFICE

GARREY CARRUTHERS  
GOVERNOR

February 13, 1990

POST OFFICE BOX 1980  
HOBBS, NEW MEXICO 88241-1980  
(505) 393-6161

Doyle Hartman  
P.O. Box 10426  
Midland, TX 79702

Attn: Michael Stewart

Re: Dabbs #2-E  
Sec. 34, T25S, R37E

Gentlemen:


Following your conversation with Evelyn Downs of this office concerning the perforations in the above-referenced well being in the Langlie Mattix Pool rather than the Jalmat Pool, our Geologist, Paul Kautz, has examined the workover report filed by Getty for work performed in February 1982 and concurs with you, that the perforations 3185--3235' are in the Langlie Mattix Pool.

In order to get this well placed in the correct pool and to eliminate the need for you to reduce the 320-acre proration unit established for the Dabbs #3-M, please file a C-104 for the Dabbs #2-E placing it in the Langlie Mattix Pool and showing perforations as 3185-3235'.

Please give us a letter reflecting the history of this recompletion. We will make this pool change effective with the approval of the C-104 and see no need to go back and correct production reports if that is satisfactory with you.

Very truly yours,

OIL CONSERVATION DIVISION

  
Jerry Sexton  
Supervisor, District I

ed

P.S. Please submit a revised acreage dedication plat, Form C-102, for Dabbs #3 removing the #2 well since it is not a Jalmat well.

per Paul Kautz,  
OCD, Geol. { Langlie Mattix 3134'  
Queen 3234'