Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5 Lease Designation and Serial No.

LC-032510(b)

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoi  Use "APPLICATION FOR PERMIT—" for such proposals	6 If Indian, Allottee or Tribe Name f.
SUBMIT IN TRIPLICATE	7 If Unit or CA. Agreement Designation
Type of Well  Oil Gas Well Other	8. Well Name and No.
Name of Operator	GREGORY C A/C 1 # 3
MERIDIAN OIL INC.	9. API Well No.
Address and Telephone No	10. Field and Pool, or Exploratory Area
P.O. BOX 51810 MIDLAND, TEXAS 79710-1810 688-6800	LANGLIE MATTIX 3 4 4 6 3
Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State
Unit 3, 1980 FSL & 1980 FEL	
Sec. 35, T-25-S, R-37-E	LEA COUNTY
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE. REF	PORT. OR OTHER DATA
TYPE OF ACTION	
TYPE OF SUBMISSION  X Abandonment	Change of Plans
Notice of intent  Recompletion	New Construction
<del>*</del>	Non-Routine Fracturing
Subsequent Report Plugging Back  Casing Repair	Water Shut-Off
Alberta Casina	Conversion to Injection
Final Abandonment Notice  Other	Dispose Water
	Note: Report results of multiple completion on We Completion or Recompletion Report and Log form
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of st give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  /23/92 - MIRU P &A Equip. RIH w/tbg to top of cmt rtnr at 3210±.  pd 10 sxs of Class C Cmt on top of rtnr. P00H to 2290. Spotted w.  OH. Stood back 1180 and LD rest of tbg. SION.  /29/92 - ND BOP. ND WH on 5 1/2 lift sub. Removed slips. Called B.  wireline. RIH w/jet cutter & cut csg. RD wireline. RIH open enders of Class C cmt. PUH to 750. Sumped 30 sxs of Class C cmt. P0H.  /30/92 - RIH w/tbg. Tagged stub plug @ 643. P0H to 400'. Circ 105 rf. P0H. LD tbg. Washed out tbg. RDMO. Capped & installed dry hole.	Circ w/mudladen fluid. 1/25 sxs of Class C cmt. SLM. Approval to cut csg. 2d tbg to 1120. Pmped 20 SDON. 35 sxs of Class C cmt to
14. I hereby certify that theiforegoing is true and correct Production Assistant	1/7/93
Signed Title	Date
(This space for Federal or State office use)	Date
Approved by Conditions of approval, if any:	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5 Lease Designation and Serial No. LC-032510 (b)

SUBMIT IN TR	RIPLICATE	7 If Unit or CA. Agreement Designation	
ype of Well  X Orl Gas Well Other		8. Well Name and No. 7 #3	
Name of Operator Meridian Oil Inc.		9. API Well No.	
Address and Telephone No.  P.O. Box 51810, Midland, TX 7971  Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area	
<i>J</i> Unit ≈, 1980 FSL & 1980 FEL Sec. 35, T-25-S, & R-37-E		11 County or Parish, State	
CHECK APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE.	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF A	TYPE OF ACTION	
Notice of Intent  Subsequent Report	Abandonment Recompletion Plugging Back	Change of Plans  New Construction  Non-Routine Fracturing	
Final Abandonment Notice	Casing Repair Altering Casing Other	Water Shut-Off Conversion to Injection Dispose Water Note Report results of multiple completion on V Completion or Recompletion Report and Log for	
Notify Hobbs BLM Office prior to workstring to location. PU works retainer. Pull up above plug and and set a cement plug across the cement. POOH.  Cut off casing at 1120' and POOH set cement plug across casing stu above plug and sopt 9 ppg gelled circulate cement to surface using off casing 3' below ground level location.	string and RIH to retainer. I sopt 9 ppg gelled brine up base of the salt at 2170' to laying down casing. RIH will be at 1060' to 1180' using 3 brine up to 400'. Pull up 105 sxs of cement. POOH 1	Spot 10 sxs of cement on to 1060'. Pull up 2290' o 2290' using 15 sxs of th tubing to 1180' and sxs of cement. Pull up to 400' and aying down. RDMO PU. Cut	