

DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.B.		
LAND OFFICE		
OPERATOR		

P. O. BOX 2088
 ANTA FE, NEW MEXICO 87501

Form C-103
 Revised 12-1-

3a. Indicate Type of Lease
 State ☒ Fee ☐
 5. State Oil & Gas Lease No.
 B-229

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☐
 Name of Operator
 Gulf Oil Corporation
 Address of Operator
 P. O. Box 670, Hobbs, NM 88240
 Location of Well
 UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM
 THE East LINE, SECTION 36 TOWNSHIP 25S RANGE 37E NMPM.

7. Unit Agreement Name
 8. Farm or Lease Name
 Arnott-Ramsay (NCT-F)
 9. Well No.
 3
 10. Field and Pool, or Wildcat
 Justis Gas
 12. County
 Lea

15. Elevation (Show whether DF, RT, CR, etc.)
 3050' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER <u>Equip to Pump</u>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with tubing and packer. RIH with 2-3/8" tubing and SN; SN at 4576'.
 Ran pump and rods, clamp off. Install pumping equipment, PNG. POH with
 rods, well parted. RIH with pump and rods, hung on. Pumping 2 BO, 17 BW
 with 54 MCF gas. Complete after equip to pump 2-23-82.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RD Pitre TITLE Area Engineer DATE 3-17-82
 ORIGINAL SIGNED BY
 JERRY SEYTO
 APPROVED BY JERRY SEYTO TITLE DATE MAR 18 1982
 CONDITIONS OF APPROVAL, IF ANY: