

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65

OF COPIES RECEIVED		
DISTRIBUTION		
IT A FE		
LE		
S.G.S.		
AND OFFICE		
OPERATOR		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR OPERATIONS TO BE DONE ON TWO OR MORE DIFFERENT RESERVOIRS. USE "APPLICATION FOR LEASE" FOR LEASES OF TWO OR MORE RESERVOIRS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator Gulf Oil Corporation	5. State Oil & Gas Lease No.
3. Address of Operator Box 670 Hobbs, NM 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 25-S RANGE 37-E N.M.P.M.	8. Name of Lease Name Arnett- Ramsay (NCT-F)
	9. Well No. 3
	10. Field and Pool, or Wildcat Justis Glorieta gas
15. Elevation (Show whether DF, RT, GR, etc.) 3050' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull producing equipment. Set CIBP at 4730' and cap with 10' of cement, abandoning perfs 4747 to 4820'. Test casing with 500#. Perforate in the interval 4634 to 4679' with 2, 1/2" JHPF. Acidize new perfs with 3500 gallons 15% NE FE HCL acid. Swab and test well.

I, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Stone TITLE Area Engineer DATE August 12, 1977

Orig. Signed by
John P. Stone

PROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: