| Submit 3 Copies To Appropriate District Office   | State of New Mexico   |                                | Form C-103<br>Revised March 25, 1999                    |
|--|---|--------------------------------|---|
| District I<br>1625 N. French Dr., Hobbs, NM 87240  | l gy, Minerals and Natural  | Resources WELL A               |   |
| District 11  | OIL CONSERVATION D  | IVISION 5 Indian               | te Type of Lease  |
| 811 South First, Artesia, NM 87210<br>District III   | 2040 South Pacheco  | J. Illuica                     |   |
| 1000 Rio Brazos Rd., Aztec, NM 87410   | Santa Fe, NM 87503  | 31                             | ATE X FEE   |
| District IV<br>2040 South Pacheco, Santa Fe, NM 87505  | <b>Suntin</b> 2 2, 1 2 2 2 2 2  | 6. State                       | Off & Gas Lease No.                                     |
| (DO NOT USE THIS FORM FOR PROPOS   | CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUGATION FOR PERMIT" (FORM C-101) FOR | G BACK TO A SOUTH              | Name or Unit Agreement Name<br>JUSTIS UNIT "G" WELL #27 |
| 2. Name of Operator HENRY PETROLEUM LP   |   | 8. Well                        | No. 27  |
| 3. Address of Operator 3525 ANDREWS HIGHWAY - SUITE 200 MIDLAND TX 79703-5000  |   |                                | name or Wildcat<br>-BLINEBERY-TUBB-DRINKARD             |
| 4. Well Location   |   |                                |   |
| Unit Letter B : 330 feet from the NORTH line and 1650 feet from the EAST line  |   |                                |   |
| Section 36   | Township25-S Ra   | inge 37-E NMPM                 | LEA County NEW MEXICO                                   |
| Section  | 10. Elevation (Show whether DR,   |                                |   |
|  | 3044' GR  | CM 4' Downston                 | Other Date  |
| 11. Check A<br>NOTICE OF IN<br>PERFORM REMEDIAL WORK [X  | Appropriate Box to Indicate Na<br>ITENTION TO:  PLUG AND ABANDON                              | SUBSEQUE<br>REMEDIAL WORK      | NT REPORT OF:  ALTERING CASING                          |
| TEMPORARILY ABANDON  | CHANGE PLANS  | COMMENCE DRILLING OF           | PNS. PLUG AND ABANDONMENT                               |
| PULL OR ALTER CASING   | MULTIPLE COMPLETION   | CASING TEST AND<br>CEMENT JOBS |   |
| OTHER: SET CIBP TO ISOLAT  | TE LOWER PERFS. [X]   | OTHER:                         |   |
| <ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.</li> <li>FISH RODS &amp; LAY DOWN BAD RODS.</li> <li>SCAN TUBING OUT OF HOLE AND REPLACE BAD JOINTS.</li> <li>SET CIBP AT 5650'.</li> <li>RE-RUN CURRENT ROD DESIGN.</li> <li>COAT RODS WITH A CORROSION INHIBITOR DUMP BEFORE PUMPING WELL.</li> <li>PUT WELL BACK ON PRODUCTION.</li> </ol> |   |                                |   |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief.   |   |                                |   |
| i hereby certify that the intormat   |   |                                |   |
| SIGNATURE Day S.   | Johnson HILLE   | KEGULATORY TECH.               |   |
| Type or print nameROY R. JOH   | INSON _   |                                | Telephone No. (915)694-3000                             |
| (This space for State use)   |   |                                | JAN + 3 Dag   |
| •  | . entre   |                                | DATE  |
| APPROVED BY Conditions of approval, if any:  | / ITTLE   |                                | DATE  |