State of New Mexico

Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 30-025-11917 Santa Fe, New Mexico 87504-2088 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD. Artesia, NM 88210 STATE X FEE 🗌 DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B - 228 - 1SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO \mbox{A} 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) SOUTH JUSTIS UNIT "H" 1. Type of Well: WELL X WELL 8. Well No. 2. Name of Operator 29 ARCO Permian 9. Pool name or Wildcat 3. Address of Operator P.O.BOX 1610, MIDLAND, TX 79702 JUSTIS BLBRY-TUBB-DKRD 4. Well Location Feet From The SOUTH Line and 660 Feet From The EAST 2100 Unit Letter I Line LEA County Township 25\$ Range 37E Section 36 10. Elevation (Show whether DF, RKB, RT, GR. etc.) 3031 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS CHANGE PLANS TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING X OTHER: DEEPEN IN B-T-D TO 6100 & TREAT OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. PROPOSE TO: POH W/ PROD CA. 2. DEEPEN IN B-T-D F/6000 PBD TO 6100 NEW PBD. 3. ADD B-T-D PERFS & TREAT. 4. RIH W/ PROD CA. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE ___AGENT DATE 06-13-95

TELEPHONE NO.915 688-5672 TYPE OR PRINT NAME Ken W. Gosnell (This space for State Use) JUN 16 1995 1110 TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY

Gran San

RECEIVE

344

UL TOUR

WORKOVER PROCEDURE

DATE: June 13, 1995

WELL & JOB: SJU H-29, DO cmt., add perfs. & treat DRILLED: 1960

LAST WORKOVER: 12/93, CO, added perfs. & treated FIELD: Fastis COUNTY: Lea, New Mexico

BY: J. Shields **TD:** 6290' **PBD:** 6000' **DATUM:** RKB to GL = 12.5'

PROD: 7" 23# J-55/N-80 5290' 827 Note: 103' of 7-5/8" 29.7# was run on top of 7" esg. and a DVT @4890'

LINER:

PERFORATIONS: Open Perfs: 5013-5442' (>200 holes), 5505-5649' (20 holes) & 5742-5934' (125 holes)

TUBING: SIZE: 2-3/8" WEIGHT: 4.7# GRADE: J-55 THREAD: EUE 8rd. JOINTS:190 BTM'D @5978'

MISC: TAC @4965'

PACKER AND MISC:

HISTORY AND BACKGROUND: Drilled and completed in 1960. In 1993 plugs were CO to PBD of 5913'. Perfs were added and the BTD was acidized and returned to production.

SCOPE OF WORK: Pull tbg. and rods, DO cmt. to 6100', treat new perfs, and return to production.

PROCEDURE

1. MIRU, pull CA.

- 2. TIH w/bit on Adaptable tool and DO cmt. to 6100' (may have to add water on backside to keep hydrostatic).
- 3. TOH w/Adaptable tool and run Wedge's GR/CPNL f/5900-6100', add perfs (\pm 20 holes) as per O/A eng.
- 4. TIH w/Baker "SAP" tool and treat new perfs. w/75 gals of acid per hole (± 1500 gals.). TOH w/pkr. and run CA as per production department design.
- 5. TOPS

//.E. Shields Drilling Team Leader

WELLBORE SCHEMATIC

12-1/4" hole. 9-5/8" casing @ 875'. Set w/425 sxs cmt. Circ.

South Justis Unit H #29

(ARCO Vinson Ramsay B #8) 2100' FSL & 660' FEL (I) Sec. 36, T-25S, R-37E, Lea Co., NM API 30-025-11917-00 KB 3042' Spudded 07/13/60 Completed 09/60

TOC @ 960' by TS

DVT - 4890

2-3/8" injection tubing set @ 5978'.

8-3/4" hole. 7" csg @ 6290'. Set w/827 sxs cmt. Blinebry-Tubb/Drinkard Perfs @ 5013' to 5934'.

PBD 6000' TD @ 6290'.

OFFICE OFFICE