

**OIL CONSERVATION COMMISSION**  
**HOBBS, NEW MEXICO**

February 24, 1965

Gulf Oil Corporation  
Box 980  
Kermit, Texas

Attn: W. W. Whitaker

Gentlemen:

We recommend that a packer leakage retest be taken upon your Vinson Ramsay NCT-B No. 10 in Unit 0 of Section 36, T25S, R37E, Justis (Blinbry and Tubb-Drinkard) dual completion.

The pressure span on the chart should be from 0 - 500 or 0 - 1000 so that the changes of pressures are easier to observe.

Thank you very much for your cooperation.

Very truly yours,

OIL CONSERVATION COMMISSION

Eric F. Engbrecht  
Engineer, District I

EFE:fd

cc: Mr. Joe D. Ramey, Supervisor, District I NMOCC