

x			

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

LAND OFFICE LC  
LEASE NO. LC-067988  
UNIT "M"  
Company Lse. No. 142745

JUN 10 1958

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	x		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

FEDERAL KNOX

June 3, 19 58

WELL NO. 2 IS LOCATED 330 FT. FROM FM (S) LINE AND 680 FT. FROM FM (W) LINE OF SEC. 18  
SW/4 of Section 18 24-S 38-E  
(1/4 SEC. AND SEC. NO.) (TWP.) (RANGE) (MERIDIAN)  
West Dolarhide (Clearfork) Lea New Mexico  
(FIELD) (COUNTY OR SUBDIVISION) (STATE OR TERRITORY)

THE ELEVATION OF THE DERRICK FLOOR ABOVE SEA LEVEL IS - FT.

DETAILS OF WORK

(STATE NAMES OF AND EXPECTED DEPTHS TO OBJECTIVE SANDS; SHOW SIZES, WEIGHTS, AND LENGTHS OF PROPOSED CASINGS; INDICATE MUDDING JOBS, CEMENTING POINTS, AND ALL OTHER IMPORTANT PROPOSED WORK.)

1. Run tubing to bottom open ended.
2. Spot cement plug on bottom from 6734 to 6534' (200') using 25 sacks regular neat cement.
3. Cut off 5-1/2-inch casing at 3530' and recover.
4. Run tubing to 1300 and spot cement plug from 1300' to 1200' with 40 sacks regular neat cement.
5. Place 25' plug in top of 8-5/8-inch surface casing with 10 sacks neat regular cement.

Completed as a dry hole.

I UNDERSTAND THAT THIS PLAN OF WORK MUST RECEIVE APPROVAL IN WRITING BY THE GEOLOGICAL SURVEY BEFORE OPERATIONS MAY BE COMMENCED.

COMPANY Humble Oil & Refining Company

ADDRESS Box 2347, Hobbs, N. M.

By R. G. Tonkin

TITLE Agent

