

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

M. Oil Co., Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1 Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2 Name of Operator

Texaco Exploration & Production Inc.

3 Address and Telephone No.

P.O. Box 730 Hobbs, New Mexico 88240-2528

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT G, 2310 FNL, 2310 FEL, SECTION 19, T-24-S
R-38-E

5 Lease Designation and Serial No.

NM 0349952

6 If Indian, Allottee or Tribe Name

7 If Unit or CA, Agreement Designation

8. Well Name and No. WEST

Douglas HIDE Drinkard U-#6

9. API Well No.

30-025-12216

10 Field and Pool, or Exploratory Area

QUEEN
Douglas HIDE Drinkard, TUBB

11 County or Parish, State

LEA

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. SET CIBP @ 6250', Tag @ 6250', Spot 25 SX PLUG 6250'-6150' (TUBB)
2. DISPLACE HOLE w/ SALT GEL MUD, 9.5# BRINE w/ 25# GEL PLBBL.
3. SPOT 25 SX PLUG 5300'-5200' (GLORIETA)
4. PERF 4 HOLES @ 3608' UNABLE TO PUMP INTO PERFS.
Spot 25 SX PLUG 3608'-3508' (QUEEN) Tag 3428'
5. CUT 5 1/2" CSG @ 3275', LID CSG. Spot 60 SX PLUG 3275-3175 (8 5/8 SHOE) Tag @ 3095'
6. Spot 40 SX PLUG 2760'-2660' (B-SALT) INSIDE 8 5/8" CSG (BLM NO TAG)
7. Spot 60 SX PLUG 1485'-1385' (T-SALT) Tag @ 1115', INSIDE 8 5/8'.
8. Spot 15 SX PLUG 60'-SURF (INSIDE 8 5/8" CSG)
9. CUT OFF WELL HEAD, INSTALL DRY HOLE MARKER, CLEAN LOC.

4/17/00

14. I hereby certify that the foregoing is true and correct

Signed

Gary Gourley

Title

VICE-PRESIDENT

Date

4/17/00

(This space for Federal or State office use)

Approved by

Conditions of Approval, if any:

Title

Date

APR 26 2000

(ORIG. SGD.) GARY GOURLEY

11/10/2020

2020-10-20 14:10:28

11/10/2020

2020-10-20 14:10:28

11/10/2020

2

2020-10-20

Receivo

11/10/2020

001