Form 3160-5 (June 1990)		ED STATES OF THE INTERIOR	N.M. Oil Cras. Divi 1625 N. French Dr. Hobbs, NM 98240	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LA	ND MANAGEMENT		5. Lease Designation and Serial No. NM 0349952
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals				
	Use "APPLICATION FOR	PERMIT - Tor Such p		7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE				11050
1. Type of Well Oil Gas Well Well X Other IN ECTOR				8. Well Name and No. WEST
2. Name of Operator				DOLLARHIDE DEILKARD #1
TEXACO ELP INC				30-025-12217
1.0. CBX STOP MIDE TO A STORE				10 Field and Pool, or Exploratory Area DOLLACHIDE, DEILLACD TUBBS, QUEEN.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT B, 990 FNL, 2310 FEL, SECTION 19, 11. County or Parish, State				
T-24-5, R-38-E			LEA NEW MEXICO	
OUTOUS ADDROBBIATE BOY(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
12 CHECK APPROPRIATE BOA(S) TO INDIGATE CONTROL TYPE OF ACTION TYPE OF SUBMISSION TYPE OF ACTION				
		X Abandor	ument	Change of Plans
Subsequent Report			letion	New Construction
		Plugging Casing	-	Water Shut-Off
	Final Abandonment Notice		g Casing	Conversion to Injection Dispose Water (Note Report results of multiple completion on Well
Completion or Recompletion Report and Log lori				
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 				
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent to this work.)* give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* TAG CIBP @ 6420', Spot 30 5X PLUG 6420-6068 (TUBBS) 4" LINER TAG CIBP @ 6420', Spot 30 5X PLUG 6420-6068 (TUBBS) 4" LINER Displace Hole W SALT GEL MUD, 9.5 # Beine W/25 # GEL P/BBL. Displace Hole W SALT GEL MUD, 9.5 # Beine W/25 # GEL P/BBL. 				
1. TAG CIO, HOLE WSALT GEL MUD, 9.5 # BRINE WIDS - GEL FIBOL.				
3. Spot 25 5x PLUG 5177- 5077 (GloeiETA) 3. Spot 25 5x PLUG 5177- 5077 (GloeiETA)				
3. Spot 25 5x prog 5177- Son Concercions 4. PEEF @ 3740' UNABLE TO PUMP INTO PEEFS. Spot 40 5x prog 4. PEEF @ 3740' UNABLE TO PUMP INTO PEEFS. Spot 40 5x prog				
4. FEEF @ 3740 UNHOFE 1 FE @ 3561.				
4. FEEF = 3140, OWEEN) TAG = 3561. 3740 - 3640: (QUEEN) TAG = 3561.				
5. PEEF @ 3284, UNABLE TO PUMP INTO PEEFS. Spot 40 SX PLUG				
5. HEFE 3234, (1010 The Caglo'. 3284-3035, (85/8 SHOE) TAG CAGIO'. J284-3035, (85/8 SHOE) TAG CAGIO'.				
5284-3035 (85/8 SHOE) TAG @2910'. 6. PEEF @2762', UNABLE TO PUMP INTO DEEFS. Spot 25 5x PLUG 2772'-2662; (B-SALT) TAG @2560'. 1. DEAT @1371' SOUFFZE 40 5x, (TOP SALT) TAG @1255'				
2772'- 2662; (B-SALT) 1AQ - 2502. 7. PEEF C1371', SQUEEZE 40 5x, (TOP SALT) TAQ C1255'				
T PEET O ISIT, SQUEECE IS TO THE T				
8 Spot 15 SX 60 - 3001 Alada				
9. INSTALL DEY HOLE MARKER CLEAN LOC 11				
14. I hereb	y certify that the foregoing is the and content	Tille Vice	- President	Date 4/24/00
Signed <u>1. Party</u> (Label (This space for Federal or State office use) (ORIG. SGD.) GARY GOURLE ^V Approved by Title <u>3ETROLEUM ENGINEEF</u> Date <u>NN 19 2000</u>				
Approved by File File				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent state or representations as to any matter within its jurisdiction. •See Instruction on Reverse Side