

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.

30-025-12224

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

172010

7. Lease Name or Unit Agreement Name:

UNITED Royalty 'A'-3

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other Inject

2. Name of Operator

TEXACO Exploration & Production Inc

3. Address of Operator

P.O. Box 730 HOBBS, NEW MEXICO 88240-2528

4. Well Location

Unit Letter F : 2310 feet from the NORTH line and 2310 feet from the WEST line

Section 19 Township 24-S Range 38-E NMPM LEA County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. POW w/ 2 1/16 TBG ON Y-SIDE.
2. ATTEMPT TO STRING OUT PER, TBG PARTED ON Z-SIDE TO F @3750'
3. ATTEMPT TO FISH TBG, NO SUCCESS BAD CSQ. NOTIFIED OCS GARY WINK OK'D TO SQUEEZE
4. SET PER @3300', SQZ 300 SX5 THRU QUEEN & DEINKARD WOC TAG @3523'
5. DISPLACE HOLE W/ SALT GEL MUD, 9.5# BEINER W/ 25# GEL PLBBL.
6. PERF @3245, UNABLE TO PUMP INTO PERFS, 25 SX PLUG TAG @2948'
7. SPOT 30 SX PLUG 2770-2520 (YATES, B-SALT)
8. CUT LID 5 1/2" CSQ @2000, SPOT 50 SX PLUG 1950-2050, TAG @1920'
9. SPOT 60 SX PLUG 1390-1190, (T-SALT)
10. PERF @425, UNABLE TO PUMP INTO, SPOT 60 SX 13 3/8 SHOE TAG @287'
11. IS SX 30-SURF. INSTALL DRY HOLE MARKER CLEAN LOC 4/11/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Poly Abalos

TITLE

Vice-President

DATE

4/11/00
(915)

Type or print name

POLY ABALOS

Telephone No. 683-4996

APPROVED BY

Camy W. Hill

TITLE

DATE

Conditions of approval, if any:

CWW

4