NO. OF COPIES RECEIVED						
DISTRIBUTION				Form C-103 Supersedes Old		
SANTA FE				C-102 and C-103		
FILE	NEW MEXICO OIL CONSE	RVATION COMMISSION		Effective 1-1-65		
U.S.G.S.			r	5c. Indicate Type of Lease		
LAND OFFICE				State State Fee		
CPERATOR			-			
OFERATOR				5. State Cil & Gas Lease No.		
(DO NOT USE THIS FOR PROUSE "APPLICAT	Y NOTICES AND REPORTS ON W POSALS TO DRILL OR TO DEEPEN OR PLUG BAC IN FOR PERMIT - (FORM CIOL FOR SLCH Dual Queen 011 and	ELLS in to a different reservoir proposals.)		7. Unit Aareement Name		
OIL GAS	OTHER-Tubb-Drinkard Water	Injection	West Do	llarhide Drinkard Unit		
2. Name of Operator				8. Farm or Lease Name		
Skelly 011 Company			West Do	llarhide Drinkard Unit		
3. Address of Operator		9, Well Nc.				
P. O. Box 1351, Midlan		5				
4. Location of Well				1 . Field and Pool, or Wildoat		
	B10 FEET FROM THE North	2310	FEET FROM	Dollarhide Tubb-Drinka		
	19 24S	397	NMPM.			
		i., County				
	15, Elevation (Show whether D	3176' GR		Lea		
16. Check	Appropriate Box To Indicate Na	ture of Notice Rope				
	TENTION TO:	SUBSEQUENT REPORT OF:				
			·			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.		PLUS AND ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOE	· [_]			
OTHER Perf. and acidize	additional pay X	CTHER				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Queen Zone is operated as an oil well by Texaco, Inc., as their United Royalty "A" Well No. 3. We propose opening additional pay in the Main Drinkard and Upper Abo Zones as follows to permit proper flooding of the entire Main Drinkard:

1) Check for fill inside the 5-1/2'' OD casing with wireline.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

- 2) Perforate 5-1/2" OD casing 6548-6598', 6602-6616', 6698-6700', 6709-6717', 6744-6747' and 6752-6758' with 2 holes per foot.
- 3) Acidize perfs. 6584-6758' with 6700 gals. 15% DS-30 acid in 5 stages using rock salt as a diverting agent.
- 4) Resume injection.
- 5) After approximately 2 weeks of stabilized injection, run injection profile.

SIGNED	D. R.	Crow	TITLE	Lead Clerk	DAT	Dec. 1	, 1972
APPROVED BY	•	· · · ·	T176E		DAT		
CONDITIONS OF APPROVAL, IF ANY:	•						