

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-12240

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-9519

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☐

OTHER Water Injection

2. Name of Operator

Sirgo Operating, Inc.

3. Address of Operator

P.O. Box 3531, Midland, Texas 79702

8. Well No.

7

9. Pool name or Wildcat

Dollarhide Queen

7. Lease Name or Unit Agreement Name

West Dollarhide Queen Sand  
Unit

4. Well Location

Unit Letter E : 2310 Feet From The North Line and 330 Feet From The West Line

Section 29 Township 24S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-15-90 RIH w/CR Set @ 3600', Squeeze 45 sx Class C cmt. Spot 5 sx on top. Pull up hole & circ w/10.2 brine + 25# salt gel/bbl. POH.  
Perf @ 2620'. RIH w/CR. Set @ 2520', Squeeze 30 sx Class C cmt, spot 5 sx on top. Perf @ 1325'. RIH. Set CR @ 1090', Squeeze 45 sx, spot 5 sx on top. Pump 30' cmt to surface. Cut off wellhead & install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bonnie Atwater

TITLE

Production Technician

DATE

1-31-90

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Jack Griffin

TITLE

OIL & GAS INSPECTOR

DATE

APR 26 1990

CONDITIONS OF APPROVAL, IF ANY: