

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-12241
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9519
7. Lease Name or Unit Agreement Name: WEST DOLLARHIDE
Drinkard
8. Well No. 21
9. Pool name or Wildcat DOLLARHIDE Drinkard, Tubb

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other **INJECTOR**

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
P.O. Box 730 HOBBS NEW MEXICO 88240-2528

4. Well Location
Unit Letter **E** : **1980** feet from the **NORTH** line and **660** feet from the **WEST** line
Section **29** Township **24S** Range **38E** NMPM **LEA** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. NOTIFY OCD, SPZ UNDER PKE @ 6575' w/ 50 SXS, TAG 6580'
2. DISPLACE HOLE w/ SALT GEL MUD 9.5# BEINE w/ 25# OF GEL P/BBL.
3. SPOT 40 SX CMT 3708-3998 (GRAY BUEY)
4. SPOT 20 SX CMT 3100-3200 (SHOE) TAG @ 2980'
5. SPOT 20 SX CMT 2580-2680 (B-SALT) TAG 2520'
6. SPOT 20 SX CMT 1293-1393 (T-SALT) TAG @ 1242'
7. SPOT 15 SX CMT 60'-SURF.
8. INSTALL DRY HOLE MARKER, CLEAN LOC. 3/21/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Poly Abalos TITLE VICE-PRESIDENT DATE 3/21/00
(915) Telephone No. 683-4996

Type or print name
(This space for State use)
POLY ABALOS

APPROVED BY [Signature] TITLE _____ DATE _____
Conditions of approval, if any:

JC GWW