Submit 3 Copies to Appropriate District Office

ì

OIL CONSERVATION DIVISION 2040 Pacheco St.				WELL API NO.	WELL API NO. 30-025-12244	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			sIndicate Type of	of Lease		
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410				⇒State Oil & Gas B-9519	STATE FEE FEE	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				- Lease Marrie C	⁻ Lease Name or Unit Agreement Name West Dollarhide Drinkard Unit	
Type of Well: OIL GAS WELL GAS WELL OTHER Injection						
₂Name of Operator Texaco E & P Inc.				∍Well No. 14		
Address of Operator P. O. Box 3109 Midland, Texas 797	02			Pool name or Dollarhide,	^{Wildcat} Drinkard, Tubb, Queen	
:Well Location Unit Letter <u>D</u> : <u>990</u> ∣	Feet From The North		Line and 33	0 Feet From	The West Line	
Section 29	Township 24S	R	ange 38E		Lea County	
	Delevation (Show wheth				Outiny	
³¹ Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INT	ENTION TO:		SU	BSEQUENT	REPORT OF:	
	PLUG AND ABANDON		REMEDIAL WORK			
	CHANGE PLANS		COMMENCE DRILLING OPNS.			
PULL OR ALTER CASING	ALTER CASING CASING TEST AND CEMI			EMENT JOB]	
OTHER:			OTHER:			
Describe Proposed or Completed Operations (<i>Clearly state all pertinent details</i> , and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-11-00 Notify NMOCD of intent to plug 2-14-00 MIRU 2-15-00 Drill out CIBP @ 6170' 2-16-00 Received OK to squeeze 40 sxs cmt @ 6170' as per Buddy H. w/ NMOCD 2-17-00 Squeeze 40 sxs cmt below 6170' 2-18-00 Well still flowing; Sqz 40 sxs cmt below 6170'; WOC; Didn't hold; Sqz 40 sxs cmt below 6170' 2-21-00 Well still flowing; Sqz 40 sxs cmt below 6170'; WOC; Flow stopped; Tag TOC @ 6018' 2-22-00 Circ hole w/ 10# mud; Spot 25 sxs cmt @ 5400'; Spot 40 sxs cmt @ 4028'; Spot 25 sxs cmt @ 3200'; WOC; Tag TOC @ 3010' 2-23-00 Spot 25 sxs cmt @ 2700'; WOC; Tag TOC @ 2546'; Spot 25 sxs cmt @ 1418' 2-24-00 Tag TOC @ 1231'; Spot 10sxs cmt from 50' to surface; RDMO 2-29-00 Cut of wellhead and install dry hole marker						
I hereby certify that the information above is tr	ue and complete to the best of my k	mowledg	ge and belief.			
SIGNATURE	KI	TITL	E Key Energy, P a	& A Supervisor	DATE	
TYPE OR PRINT NAME Noel Allen					TELEPHONE NO. (915) 523-5155	
(This space for State Use) APPROVED BY	D. Lief	ΤΙΤΙ	E		DATE	
CONDITIONS OF APPROVAL IF ANY: $//$						