

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30 025 12244
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. B-9519

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Injector	Lease Name or Unit Agreement Name West Dollarhide Drinkard Unit
Name of Operator Texaco E&P Inc.	Well No. 14
Address of Operator P.O. Box 3109, Midland, Texas 79702	Pool name or Wildcat Dollarhide, Drinkard, Tubbs, Queen
Well Location Unit Letter <u>D</u> : <u>990</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>29</u> Township <u>24S</u> Range <u>38E</u> NMPM Lea County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify OCD of intent to plug
- 2) MIRU, NU BOP
- 3) Set CIBP @ 6650, mix and circulate 10# mud, cap w/20 sx (Drinkard)
- 4) Spot 20 sx cement fm 6200-6300 (Tubbs)
- 5) Spot 20 sx cement fm 5300-5400 (Glorieta)
- 40 6) Spot ~~20~~ sx cement fm 3738-3838 (Queen) **3738-4028 Grayburg**
- 7) Spot 20 sx cement fm 3100-3200 (8 5/8 shoe) WOC/Tag
- 8) Spot 20 sx cement fm 2600-2700 (b-salt) WOC/Tag
- 9) Spot 20 sx cement fm 1318-1418 (t-salt) WOC/Tag
- 10) Spot 5 sx cement fm 50'
- 11) RDMO, cut off well head, install dry hole marker, clean location

THIS COMPLETION MUST BE NOTICED 24
HOURS BEFORE THE COMMENCEMENT OF
ANY DRILLING OR CEMENTING FOR THE C103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim T. Corbitt TITLE Engineer DATE 12-01-99

TYPE OR PRINT NAME Jim Corbitt

TELEPHONE NO. (915) 688-4438

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: