Adomit 3 Copies 5 Appropriate District Office		New Mexico nural Resources Department	Form C-103 L Revised 1-1-89
DISTRICT I	OIL CONSERV	ATION DIVISION	WELL API NO.
O. Box 1980, Hobbs, NM 88240		Box 2088	30 - 025 - 12250
DISTRICT II C. Drawer DD, Artesia, NM 88210	Santa Fe, New M	lexico 87504-2088	5. Indicate Type of Lease STATE FEE
HISTRICT III	40		6. State Oil & Gas Lease No.
000 Rio Brazos Rd., Aztec, NM 874			
SUNDRY N	KOTICES AND REPORTS O	N WELLS	
DIFFERENT R	PROPOSALS TO DRILL OR TO D ESERVOIR. USE "APPLICATION I RM C-101) FOR SUCH PROPOSAL	FOR PERMIT"	7. Lease Name or Unit Agreement Name
Type of Well:			WEST DOLLARHIDE DRINKARD UNIT
OL GAS WELL WELL	OTHER IN	jection Well	
Name of Operator			8. Well No.
Texaco Exploration and Address of Operator	Production inc.	·····	9. Pool name or Wildcat
P. O. Box 730 Hob	bs, NM 88240		DOLLARHIDE TUBB/DRINKARD
Well Location		t.	AD10 WEST -
Unit Letter <u>C</u> :	535 Feet From The Nort	in Line and	2310 Feet From The KEST L County
Section 30	Township 24-S	Range 38-E	NMPM LEA
	<i></i> .	whether DF, RKB, RT, GR, etc.)	
~		' GR, 3156' KB	Percent as Other Data
	ck Appropriate Box to Inc		UBSEQUENT REPORT OF:
NOTICE OF	INTENTION TO:		
ERFORM REMEDIAL WORK	PLUG AND ABANDON		ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS		UNG OPNS. 🔲 PLUG AND ABANDONMENT
JLL OR ALTER CASING]	CASING TEST AND	
THER:		OTHER: Convert	
2. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent	details, and give pertinent dates, is	ncluding estimated date of starting any proposed
		-	
. MIRU. Pulled rods and	pump. Installed BOP. Pulle	ed tubing.	
 TIH w/ bit and casing Ban casing inspection 	scraper. Cleaned casing log 6909' to surface. Se	to 6787'. t CIBP @ 6730' canned	tw/10 ³ cement.
Acidized Drinkard w/	1500 gals 15% NEFE.		
5. Ran 2-3/8" polyethyle	ene lined injection tubing v ad Tested annulus to 300	with packer set at 656) osi for 30 minutes.(Ch	hart attached, copy on reverse)
Elanged up tubing her			
 Flanged up tubing heat 10-06-93: Inject 177 			
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test and 	nd profile when rates stab	ilize.	
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test and 		ilize.	
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test and 	nd profile when rates stab	ilize.	
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test an Previous production 1 	nd profile when rates stab test= 6 oil, 39 wtr, 1 MCF	ilize.	
 6. Flanged up tubing head 7. 10-06-93: Inject 177 8. Run step rate test an Previous production to Previous production to WEX-6 	d profile when rates stab test= 6 oil, 39 wtr, 1 MCF 4と	ilize.	
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test an Previous production 1 WI-X-b I hereby cartify that the information above 	nd profile when rates stab test= 6 oil, 39 wtr, 1 MCF <u>4.6</u> w is true and complete to the best of my know	vilize. wiodge and belief.	
5. Flanged up tubing heat 7. 10-06-93: Inject 177 8. Run step rate test an Previous production to W = X - b I hereby certify that the information above SKONATURE	ad profile when rates stab test= 6 oil, 39 wtr, 1 MCF 4 $2e is true and complete to the best of my know$	ilize.	DATE01-11-94
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test an Previous production 1 WI-X-b I hereby cartify that the information above 	ad profile when rates stab test= 6 oil, 39 wtr, 1 MCF 4 $2e is true and complete to the best of my know$	vilize. wiodge and belief.	DATE01-11-94 TELEPHONE NO.505-393-
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test an Previous production to Previous production to Previous production to Previous production above skinkature with the information above skinkature with the in	nd profile when rates stab test= 6 oil, 39 wtr, 1 MCF 4 & e is true and complete to the best of my know 	widge and belief. TTTLEEngr Asst	
 Flanged up tubing heat 10-06-93: Inject 177 Run step rate test an Previous production to Previous production to Previous production to Previous production above skinkature with the information above skinkature with the in	ad profile when rates stab test= 6 oil, 39 wtr, 1 MCF 4 $2e is true and complete to the best of my know$	widge and belief. TITLEEngr Asst TON	TELEPHONE NO.505-393-
5. Flanged up tubing hea 7. 10-06-93: Inject 177 8. Run step rate test an Previous production 1 <i>WEX-b</i> I hereby certify that the information above SKONATURE <i>WEALS</i> TYPE OR PRINT NAME L.W. Joh (This space for State Use) ORIG	INAL SIGNED BY JERRY SEX	widge and belief. Engr Asst TTTLEENGR Asst TON	

de

