Submit 3 Copies To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Resources			Form C-10 Revised March 25, 19	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.		
1301 W. Grand Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-12278 5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1220 South St. Francis Dr.			STATE FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		305	6. State Oil & Gas Lease No.	$\neg$
SUNDRY NOTICES AND REPORTS ON WELLS			NM-10186 7. Lease Name or Unit Agreement Na	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				me:
PROPOSALS.) 1. Type of Well:	reading (rolling e-101) Fe	JK 30CH	West Dollarhide Drinkard Unit	
Oil Well Gas Well Other Injection				
2. Name of Operator Chevron USA, Inc.			8. Well No.	-
3. Address of Operator 15 Smith Rd. Midland, Tx 79705			9. Pool name or Wildcat	
4. Well Location			Dollarhide, Tubb, Drinkard	
Unit Letter_B : 480	feet from the north	line and 165	60 feet from the E	ne
Section 31	Township 24-S Ra	<sub>nge</sub> 38-E	NMPM County Lea	
10. Elev	vation (Show whether D		county — Cou	
11. Check Appropriat	e Box to Indicate Na	ture of Notice, R	Report or Other Data	
NOTICE OF INTENTION TO: SUB			SEQUENT REPORT OF:	_
	AD ABANDON []	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE	PLANS	COMMENCE DRIL		V
PULL OR ALTER CASING MULTIPL COMPLE		CASING TEST ANI	ABANDONMENT	
OTHER:		OTHER:		
12. Describe proposed or completed operate of starting any proposed work). SEE RUL or recompilation.	tions. (Clearly state all p LE 1103. For Multiple C	pertinent details, and completions: Attach	give pertinent dates, including estimated wellbore diagram of proposed completion	date n
1. Set 4 CIBP @ 6350 spot 35sx fr/6	350-6100(Drinkard) To	op 4 Liner Tag @ 6	6073	
<ol> <li>Displace hole w/MLF 9.5 # Brine v</li> <li>Spot 25sx plug fr/3600-3400(Quee</li> </ol>			JAN 11 5 1	
4. Spot 40sx plug fr/3075-2700(7 5/8 shoe, Yates, B-salt)Tag @ 2686				
<ol><li>Perf 4 holes @ 1400 sqz w/75sx fr</li></ol>	r/1400-1200(T-salt) Ta	a @ 1121		
6. Perf 4 holes @ 300 circ cmt fr/300 7. Install dry hole marker. 12-11-02	10 Sun W/140SX 5 1/2	x / 5/8 csgs(10 3/4	4 shoe, surf) Tag @ stirf.	
			Dr. Las	
Approved as to Plugging of the	ne Well Bore.		1, 40,00	
Liability under bond is retained	ed until			
Surface restoration is comple	ted.			
I hereby certify that the information above is tr	ue and complete to the b	est of my knowledge	e and belief	
SIGNATURE		MANAGER/SU		<u>.                                    </u>
Type or print name Jimmy BAGLEL		777		
(This space for State use)	7		Telephone No.915 <b>530-8</b> 7	<u>&gt;</u> 6
APPPROVED BY	<b>ភាពស្រ</b> ុំ	D1	MANAGER DATE	
Conditions of approval, if any:	Charles and Market	OF STAFF	MAIN OF DATE WAS 1 !	ن خط
	OCHELD REPROPE	Au factor		