

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-069052

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Dollardside Drinkard Unit

8. FARM OR LEASE NAME

West Dollardside Drinkard Unit

9. WELL NO.

47

10. FIELD AND POOL, OR WILDCAT

Dollardside Tubb-Drinkard

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

31-24S-38E

12. COUNTY OR PARISH

LEA

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL2. NAME OF OPERATOR
SKELLY OIL COMPANY3. ADDRESS OF OPERATOR
P. O. Box 1351 Midland, Texas 797014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

480' FW and 1650' FDL Sec. 31-24S-38E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

UNKNOWN

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐(Other) Convert to water injection ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

- (1) Moved in and rigged up workover rig Sept. 19, 1969.
- (2) Pulled rods and pump.
- (3) Hooked well to injection system and began pressuring up Sept. 20, 1969.
- (4) Moved in and rigged up workover rig 11-30-69.
- (5) Ran tubing and bit and cleaned out 6434-6521'.
- (6) Pulled tubing and bit.
- (7) Ran 2-3/8" OD cement-lined tubing with Guiberson 5 1/2" x 2" RMC-1 packer set at 6246'.
- (8) Loaded casing annulus behind tubing with water treated with inhibitors.
- (9) Hooked well to injection system and began injecting water on Dec. 2, 1969, into open-hole section 6400-6521' of the Drinkard Reservoir.

This is a water injection well for the West Dollardside Drinkard Unit operated by Skelly Oil Company.

18. I hereby certify that the foregoing is true and correct

SIGNED

(Signed) J. R. Avent J. R. Avent

TITLE District Office Manager

DATE December 11, 1969

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
DATE

DEC 15 1969

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.