

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002512279
5. Indicate Type of Lease	STATE FEE
6. State Oil / Gas Lease No.	172010
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	51
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL GAS WELL OTHER INJECTION
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter H : 2310 Feet From The NORTH Line and 330 Feet From The EAST Line Section 31 Township 24S Range 38E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPERATION	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	REPAIR CSG & ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/02/00: MIRU. RU REV UNIT. RU FRAC TANK & FLOWLINE.
6/05/00: NUBOP & ENVIR-VAT. TIH W/OS, GRAPPLE. PU WS. FSH @ 1616'. WRK TBG LOOSE.
6/06/00: TIH W/BIT & CSG SCRAPER ON TBG. TAG @ 6361'. TOP PERF 6410'. PULL BIT TO 4921'. PKR WAS SET @ 6241'.
6/07/00: TIH W/RBP, PKR, SN ON WS. SET RBP @ 6244'. WATER FLOW STOPPED. PULL UP & SET PKR @ 6232 & TEST RBP TO 800#-OK.
REL PKR & LOWER TOOLS TO RBP. LATCH & REL RBP. TIH W/CONE BUSTER MILL, DC'S ON TBG TO 5755'.
6/08/00: TIH W/MILL & TBG. TAG @ 6361'. C/O SCALE & IRON SULFIDE 6361-6446. PLUGGED MILL. STOP MILL @ 1749'.
6/09/00: RERUN MILL ON TBG. / MILL 6446-6455'. TIH W/KILL STRING TO 1878'.
6/12/00: TIH W/PKR, SN ON TBG. TRY TO SET PKR @ 6333'. PULL UP TO 6302' & SET PKR. PRES CSG TO 500#-OK. ACIDIZE DRINKARD
PERFS 6410-6455 W/3000 GALS 15% NEFE HCL.
6/13/00: REL PKR & PULL UP TO 6239-SET PKR. TEST BACKSIDE TO SURF TO 500#-OK. REL PKR.
6/14/00: TIH W/TBG. RAN 199 JTS 2 3/8" TBG. NDBOP. PKR SWINGING @ 6247'. SET PKR @ 6247. TEST & CHART CSG FOR NMOC TO 500#-
30 MIN-OK. NU INJ HDR. RIG DOWN.
7-27-00: ON 24 HR OPT. INJ'G 210 BWPD @ 1330 PSI. FINAL REPORT

Note: E.L. Gonzalez or Buddy Hill with the NMOC
took the chart after witnessing the test

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE J. Denise Leake TITLE Engineering Assistant
TYPE OR PRINT NAME J. Denise Leake

DATE 8/22/00

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY TITLE DATE