Form 3160-5 UNITFO STATES (No rember 1983)	SUBMIT IN TRIPLICATION (Other Instructions o
(Furmerly 9-331) DEPARTMEN OF THE INTE	verse side)
BUREAU OF LAND MANAGEMEN SUNDRY NOTICES AND REPORT	CON WELLS GENDAN ALOTTE ORTHON NAME
(Do not use this form for proposals to drill or to deepen or plu  Use "APPLICATION FOR PERMIT" for such	proposals.)
t -	7. UNIT AGREEMENT NAME
OIL GAS OTHER INJECTION	1 kg. 12 3 4 4
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
OXY USA INC.	W. DOLLARHIDE QN SD UT
3. ADDRESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 797	1 22
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirer See also apace 17 below.)</li> <li>At surface</li> </ol>	DOLLARHIDE QUEEN  11, SEC., T., R. M., OR BLK, AND
1750 FNL 2310 FWL SE-NW	SURVEY OR AREA SEC 31 T24S R38E
Let II DATOM Franches DE II	40 COLBUTY OF PATICULAR STATE
14. PERMIT NO. 15. ELEVATIONS (Showwheter DF, R	3114 LEA NM
300251228500S01	3114
Check Appropriate Box To Indicate Nature of Notices, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:	
TESTWATER SHUT-OFF PULL OR ALTER CASING MALTIPLE COMPLETE ABANDON* CHARGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACCIDIZING  (Other) SET CIBP & ISOLATE ZONE (Note: Report results of multiple completion on Well
proposed work. If well is directionally drilled, give subsurfit nent to this work.)*  TD - 3975' PBTD - 3660	PERFS - 3602' - 3660'
MIRU PU 10/25/94, NDWH, NUBOP, POOH W/ PKR & TBG. RIH W/ CIBP & SET @ 3670' & DUMP 10' CMT ON TOP. RIH W/ BAKER AD-1 PKR & 2-3/8" TBG, TAG CEMENT @ 3660'. NDBOP, CIRC W/ PKR FLUID, SET PKR @ 3490', NUWH. TEST CSG TP 370#, HELD OK, CHARLIE PERIN W/ NMOCD WITNESSED TEST, RDPU 10/26/94. PUT WELL BACK ON INJECTION.	
	ACCEPTED FOR RECORD  NOV 10 1994  CARLSBAD, NEW MEX
16. Thereby certify that the foregoing is true and correct SIGNED	REGULATORY ANALYST DATE 11/2/94
(This space for Federal or State office use)	
APPROVED BY TITLE	DATE

## \*See Instructions on Reverse Side

CONDITIONS OF APPROVAL, IF ANY:

