

NEW MEXICO OIL CONSERVATION COMMISSION

3- NMOCD-Hobbs, Lea County
1- Mr. Frnka-Tulsa
1- Mr. R.W. Blohm-Midland
1- JDM
1- File

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM AND PROCEED TO OIL OR GAS WELL OR TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT AND PLUGGING CASES FOR SUCH PROCEEDINGS.)

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

West Dollarhide Drinkard

8. Farm or Lease Name

West Dollarhide Drinkard

9. Well No.

65

10. Field and Pool, or Wildcat

Dollarhide-Tubb-Drinkard

12. County

Lea

15. Elevation (Show whether DF, RT, GR, etc.)

3125 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIATION WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER Recement casing ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit.
2. Install BOP and pull tubing.
3. Set cement retainer at 6580'.
4. Run CBL.
5. Squeeze off abo through retainer
6. Perforate two holes above cement top.
7. Set retrievable bridge plug below cement top.
8. Spot acid and attempt to break circulation.
9. Pump red dye to determine cement volume.
10. Circulate cement to surface and squeeze.
11. Drill out cement after WOC 24 hrs.
12. Remove RBP
13. Acidize with 4800 gallons 15% HCL.
14. Run tubing and return well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David R. Crockett

TITLE Area Superintendent

DATE 7/30/80

APPROVED BY David R. Crockett

TITLE Area Superintendent

DATE AUG 2 1980