## STATE OF NEW MEXICO

ENERGY	ONA	MINERALS	DEPARTMENT

THO I AND WINNEHALS DE	PAH	INE
( +4( 6) +6	T	
DISTRIBUTION	}	
SANTA FE		
FILE		
U.S.G.S.	Ι	
LAND OFFICE		
	_	

## OIL CONSERVATION DIVISION P. O. BOX 2088

## SANTA FE, NEW MEXICO 87501

Fo	ΓĦ	C	-	10	"					
Re	٧i	s e	d	1	0	-	1	-	7	į

SA. Indicate Type	of Lease
STATE X	, rec 🔲
.5. State Oll & Gas	Lease No.
D 0011	

APPLICATION FOR PERMI	T	TO DRILL	, DEEPEN	OR	PLUG	BACK

la. Type of Work					<del></del>			ement Name
b. Type of Well	DRILL			EEPEN 🗌	SINGLE 🔯	PLUG BACK X	8. Farm or L Mexico	**
3 None of Opposite		OTHE		····	ZONE X	ZONE		J
2. Name of Operator Texac	o Producin	g Inc.					9. Well No.	
3. Address of Opera	tor						10. Field on	d Pool, or Wildeat
P. O.	Box 728,	Hobbs,	New Mexic	o 88240			Wildca	t
4. Location of Well			-		PEET FROM THE			
AND 1980	FEET FROM THE	East	LINEO	r sec. 32	TWP. 24-S R	E. 38-E NMPM	777777	
							12. County Lea	
		//////			19. Proposed Dept	h 19A. Formation		20. Rotary or C.T.
					3560' PBT	D Yates		Pulling Unit
.I. Elevations (Show	whether DF, KT,	etc.)	21A. Kind & S	tatus Plug. Bond	21B. Drilling Cont	ractor	22. Approx	. Date Work will start
3170	DF	- 1	ī	Rlanket	ł		Mary 2	1 1000

## PROPOSED CASING AND CEMENT PROGRAM

	SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
٠	18"	13-3/8"	48#	300'	300	Circulated
	12-1/4"	8-5/8"	36#	3155	1700	Circulated
	7-3/8"	5-1/2"	17#	10,300'	843	3406 CBL

1. MIRU.

23.

- 2. POH w/rods & pump. Kill well. Install BOP. Pull tubing.
- 3. Run GR-CNL from 3600' to Surface.
- GIH w/CIBP via wireline & set at top of Queens formation (approximately 3590').
- Dump 30' cement on top of CIBP (New PBTD 3560').
- Test 5-1/2" casing to 1800 psi.
- Perforate per GR-CNL log.
- TIH w/tubing & packer. Set packer 30' above top perf.
- 9. Acidize perfs w/5,000 gallons NEFE acid.
- 10. Swab to test.

ORIGINAL SIGNED BY JERRY SEXTON	
I hereby certify that the information above is true and complete to the best of my know  J. A. Sch  Signed  Title  Dist. Ope	

RECEIVEL

MAY 24 7008

OCD EHOBBS OFFICE