

Submit 3 Copies To Appropriate District  
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-12299

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-9311

7. Lease Name or Unit Agreement Name:

New Mexico J

8. Well No.

5

9. Pool name or Wildcat  
Blinebry

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Chevron USA, Inc.

3. Address of Operator

15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter L : 1980 feet from the south line and 660 feet from the west line

Section 32

Township 24-S

Range 38-E

NMPM

County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH Tag 5 1/2 CIBP @ 5395 spot 25sx plug 5395-5195(Blinebry)Tag @ 5168

2. Displace hole w/MLF 9.5# Brine w/25# Gel P/BBL.

3. Spot 25sx plug fr/3700-3500(Queen)

4. Spot 65sx plug fr/3200-2600(9 5/8 shoe,B-salt,Yates)Tag @ 2582

5. Spot 25sx plug fr/1400-1200(T-salt)Tag @ 1161

6. Perf 4 holes @ 300 unable to sqz spot 40sx plug fr/350-surf Tag @ surf( 13 3/8 shoe)

7. Install dry hole marker. 12-18-02

Approved as to Plugging of the Well Bore.

Liability under bond is retained until

Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE MANAGER/SUNSET

DATE 12/18/02

Type or print name

Jimmy BAGLEY

Telephone No. 915520-8756

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

JAN 09 2003

ORIGINAL FORWARDED BY  
CARY W. JONES  
EXTENDED STATE CONTRACTS & LEASES MANAGER

9

sent 2/1/03