

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-025-12310

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-9311

7. Lease Name or Unit Agreement Name:

West Dollarhide
Drinkard Unit

8. Well No.

71

9. Pool name or Wildcat

Dollarhide, Tubb, Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ Injector

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address of Operator

P. O. Box 3109, Midland, TX 79702

4. Well Location

Unit Letter P : 810 feet from the South line and 510 feet from the East line

Section 32

Township 24S Range 38E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Set 4" CIBP @ 6350' (Tubb-Drinkard) Spot 25 Sx plug 6350'-6100'. WOC Tag
- Displace hole w/MLF 9.5# Brine w/25# gel P/BBL
- Spot 25 Sx plug 3600'-3350' (Queen)
- Perf 6 holes @ 3200' (8 5/8" shoe, B-Salt Yates) Sqz 125 Sx plug 3200'-2700'. WOC Tag
- Perf 6 holes @ 1200' (T-Salt) Sqz 75 Sx plug 1200'-900' WOC Tag
- Spot 10 Sx Surf, 15'-Surf. Install dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Corbett TITLE FACILITY ENGR

DATE 1/22/01

Type or print name JAMES T. CORBITT

Telephone No. 915 688-4438

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

JAN 31 2001

dp