

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-12313
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9311
7. Lease Name or Unit Agreement Name West Dollarhide Drinkard Unit
8. Well No. 70
9. Pool name or Wildcat Dollarhide Tubbs Drinkard
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Exploration & Production, Inc.
3. Address of Operator P.O. Box 3109 Midland, Texas 79702	4. Well Location Unit Letter 0 : 2130 Feet From The East Line and 510 Feet From The South Line Section 32 Township 24S Range 38E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 2/3/98 Tagged plug @5460' CIRC hole w/mud laden fluid
2. 2/4/98 Spot 25 sx cmt @3632' to @3385'
3. 2/4/98 Spot 25 sx cmt @3194' WOC, tagged @2945'
4. 2/4/98 Spot 25 sx cmt @2536' to @2289'
5. 2/5/98 Spot 25 sx cmt @1315' to @1068'
6. 2/5/98 CIRC 40 sx cmt @345' to SURF
7. 2/10/98 Cut off wellhead, built dry hole marker and set, cut off anchors, filled in cellar and cleaned location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Russ [Signature] TITLE Div. Manager Dawson DATE 2-11-98

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Charles [Signature] TITLE Director DATE _____

CONDITIONS OF APPROVAL, IF ANY: JCT (1)

PAID IN FULL
CT 9/2/98