

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☐	OTHER- <u>Injection</u>	7. Unit Agreement Name West Dollarhide Devonian
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name Unit
Address of Operator P.O. Box 670 Hobbs, NM 88240			9. Well No. 109
Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>24S</u> RANGE <u>38E</u> NMPM.			10. Field and Pool, or WHdcat Dollarhide Devonian
15. Elevation (Show whether DF, RT, GR, etc.)			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

ORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
FORABLY ABANDON ☐	CHANGE PLANS ☐
OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 10-28-88 thru 10-29-88 TD: 8700 PB: 7765

POOH w/production equipment. Loaded BS w/140 bbls pkr fluid. Set baker lok-set pkr at 7485'. ND BOP, NUWH, pressure tested BS to 600psi, 30/min. OK. RDMOPU. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<u>L. L. Elms</u>	TITLE <u>Drilling Technical Asst.</u>	DATE <u>11-7-88</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
SIGNED BY	TITLE	DATE
REMARKS OF APPROVAL, IF ANY:		