

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
LC 060944

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Largille - Federal9. WELL NO.
210. FIELD AND POOL, OR WILDCAT
Justia - Blinbry11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 14, T-25S, R-37E12. COUNTY OR PARISH
Lea13. STATE
N.M.**SUNDRY NOTICES AND REPORTS ON WELLS**
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☒ GAS ☐
WELL WELL OTHER2. NAME OF OPERATOR
Atlantic Richfield Company3. ADDRESS OF OPERATOR
P. O. Box 1978, Roswell, New Mexico 882014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2310' FNL, 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3120' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log forms)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RU PU on 4/22/69. Pulled completion assembly. Added Blinbry perfs w/1/2" jet shot @ 5128, 5138, 5146, 5156, 5176, 5182, 5194, 5228, 5239, 5286, 5304, 5310, 5325, 5337 & 5353 (Sonic Log Mantf. Treated w/1000 gal 15% HCl acid & ball sealers. Frac'd all Blinbry perfs 5128 to 5466 w/50,000# 20/40 sand in 50,000 gal slick salt water in 5 stages, using 3 stages of rock salt to divert treatment and using temperature surveys to monitor treatment. Job was done down 2-1/2" tubing @ average injection rate of 18 BPM @ 3200#. Ran 2" tbg bottomed @ 5095.33' w/TIW-JSAC hookwall packer set @ 5086.42'. On 24 hour test ending @ 7:00 AM 4/28, well flowed 130 BNO, no water, on 14/64" choke, 625# FPP. GOR 1288/1.

18. I hereby certify that the foregoing is true and correct

SIGNED **O. D. Bretches**TITLE **Dist. Drlg. Supervisor**DATE **4-28-69**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local, Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land, should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 7: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well and date well site conditioned for final inspection looking to approval of the abandonment.