## NEW : VICO OIL CONSERVATION COMMI ON Santa Fe, New Mexico REQUEST FOR (OIL) - (GAST ALLOWARD FICE O. C. C. New Well Rovisod 7/1/57

This form shall be submitted by the operator before an initial allowable will be assigned to amp complete the or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which form C-101 was sent. The allowable will be assigned effective 7:00, A.C. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

			• • • • • • • • • • • • • • • • • • • •	•				Rosk	911.	New M	exico			11-20-	63
								(Pla	ace)					(Da	
			QUESTI												
			ining C	ombanj	7		Jal (Lease)	, W	ell No.	2	••••••••••	, i <b>n</b>	NW	1/4	NE1/4,
••••••	<b>B</b>		11	., T	258		· ·	, NMI	P <b>M.,</b>	Undes	ignat	ed Bl	inetry	、 •••••	Pool
	Letter			<b>C</b>	D	<b>c</b> _		10-1 <	-63	Det	- D-411	ine Ce	mlatad	<u>ا</u> اء	8-63
Lea			Cou Eleva	nty. Date tion	spu	3130 I	)F	Tota	l Depth	• NEILL	617	7_PBTD_			
P	Please indicate location:												Blin		<u></u>
D	C	В	A		CING INTE										
				Perfo	rations_		5290-	5310	WAL	i js	FF				
E	F	G.	H		Hole				Dent	h ng Shoe	6	176	Depth Tubing	505	2.19
				OIL W	ELL TEST	-									
L	K	J	I	-			•	bbls.o	il,	t	bls wat	er in _	hrs,	mi	Choke n. Size
													of oil ea		
M	N	0	Р	load	oil used)	:	100 bi	ols.oil,	0	bbls	water i	.n'	10.rs,	C	hoke 12/64
				GAS	ELL TEST	-									
660 FNL 2 2310 FBL				. Natur	al Prod.	Test	\$		MCF/	Day; Hou	rs flow	ned	Choke	Size	
Tubing	,Casing	and Cemen	ting Recor	d Metho	d of Test	ting	(pitot, )	pack pres	sure, e	tc.):					
Siz	Size Feet Sax		Test	After Ac	id or	Fracture	e Treatme	nt:			MCF/I	Day; Hour:	s flowed		
95	/8 9	66.14	673	Choke	e Size		Method	of Testi	ng:				:		
				Acid	or Fractu	re T	reatment	(Give amo	ounts o	f materi	als use	d, such	as acid,	water,	oil, and
7 œ	7 5/8	0104	600	1	Acid or Fracture Treatment (Give amounts of materials used, such as acid, water, sand): 1000 rego gal, acid and fraced u/24,000 # sand & 20.									1	
					9 PKR			750 Da							
				Oil	ransporte		The	Permai	n Cor	porat	ion				
				1	ransporte		Vent	ted ter	pora	rily :	endin	lg sal	les out	let	
Remark	<b>LS :</b>										·····	• • • • • • • • • • • • • • • • • • • •			
	Puall	y comp	leted w	ell	Blineta	ry 3	Tubb-	-Drinka	ard)	<u>)</u>				•••••	
$\underline{\mathcal{T}}$	4 Il	tes !	51 5-	<b>Y</b> ð	)		\ 		- a.	ul		10-1	ne_	- <del>ت</del> قوي	
/I h	nereby co	ertify the	2 <b>4</b> 9000	rmatior	ı given a	bove	is true	and com	plete t	o the be	st of m	y <b>knov</b>	vledge.		
Approv	ed	NUY	× 1 <b></b>			, 1	9	••••••	T	he.Atl	anti.c Compan	Ref:	ining C	loxpanj	
		( <b>A</b> ) ( <b>A</b> )		<b>601</b> (1)	MEETO			D	AD	I	sel	n/u	1		
		NSER	VATION	COM	M122101	N		<i>в</i> у∶	····t··· <del>·</del> ···	¥	(Si	gnature	)	A <sub>o</sub> D <sub>o</sub>	Kloxin
By:		<u>[[</u>				••••		Title					& Dril garding		upervisor
Title					•••••	<b>-</b>	••	Name.	T	he Atl	antic	Ref	ini <del>ng</del> -C	cocan	
-								Addre	<b>B</b>	ox 197	78 - F	los พอ	11, Nev	Meric	<b>:</b> 0

î

and a state of the second

. <sup>1</sup>. 1,

\_ .

z≁ <sub>a</sub>,

-<u>.</u> - .

÷. †

3.6.3

-, <sup>1</sup>.--