

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC
1-File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

a. Indicate Type of Lease	State XX	Fee <input type="checkbox"/>
b. State Oil & Gas Lease No.	E-1566-2	
c. Joint Agreement Name		
d. Form of Lease Name	STATE "BB"	
e. Well No.	2	
f. Field and Pool, or Well Unit	Justis Blinebry-Drinkard	
g. County		

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator GETTY OIL COMPANY
3. Address of Operator P.O. Box 249, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER D 430 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 25 S RANGE 37 E N.M.P.M.
5. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair Casing Leak

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work) SEE RULE 1103.

Well is a dual oil, completed in the Blinebry and Drinkard Zones using two strings of 2-7/8" casing. Packer leakage test indicated communication.

Ran 2-1/2" HOWCO RITS on 1-3/8" tubing and located hole between 5406 and 5438' in Drinkard string. Set 1" integral tubing liner (glass wrapped) from 5802' back to 5188' using Brown pack-off. Swabbed in.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By		
SIGNED G. L. WADE	TITLE Area Superintendent	DATE March 3, 1970
APPROVED BY <i>[Signature]</i>	TITLE Area Superintendent	DATE
CONDITIONS OF APPROVAL, IF ANY:		
WTC/hh		