

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-158

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name N. M. 'BZ' St. NOT-10
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 3
4. Location of Well UNIT LETTER L 989 FEET FROM THE West 1980 LINE AND FEET FROM THE South LINE, SECTION 2 TOWNSHIP 25-S RANGE 37-E NMPM.	10. Field and Pool or Wildcat Justis Blinebry Justis Tubbs Drinkard
11. Elevation (Show whether DE, RT, GR, etc.) 3173 (DF)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER Downhole Commingle ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. PULL RODS AND PUMP IN DRINKARD STRING. INSTALL BOP.
2. CLEAN OUT BLINEBRY STRING TO 6200'.
3. PERFORATE BLINEBRY STRING IN DRINKARD FORMATION W/2-JSPF @ 5883', 87', 5902', FROM 5915'- 5917'; @ 5919', FROM 5982' - 5986'; @ 5989', 98', 6006', 16', 21', FROM 6036', - 6038'; @ 6048', 52', 59', 65', 87', 6103', 24', 38', 74', & 6187'.
4. SET PKR @ 5850'. ACIDIZE PERFS 5883' - 6187' W/6200 GALS 20% LST NEFE` ACID~, 4000 GALS GELLED 2% KCL ACID, & 30 BBLs GELLED 10# BRINE IN 4 STAGES USING 300# ROCK SALT BETWEEN STAGES.
5. INSTALL PRODUCTION EQUIPMENT. TEST AND PLACE ON PRODUCTION AS DOWNHOLE COMMINGE OF TUBE/DRINKARD AND BLINEBRY ZONES.

DHC-518

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE ASST DIST MGR DATE 9-24-84

ORIGINAL NO. 11 OF 12

APPROVED BY [Signature] TITLE DATE SEP 27 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 26 1984

C.C.B.
HOBBS OFFICE