UNITEL		TATE	:S
DEPARTMENT	OF	THE	INTERIO
GEOLOG	CAL	. SUF	RVEY

COPY TO O. C. C		Form Approved. Budget Bureau No. 42-R1424			
	5. LEASL	a	: {	, a 3	
	LC-032	874 (a)	**	_ే.కర్	
	6. IF INDIAN	, ALLOTTEE C	R TRI	BE NAME	

DEI ARTIMERT OF THE INTERIOR	10-0320 (4 (a)				
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
	- 0 0 1 2 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
OUNDDY MOTIOTE AND DEPORTS ON WELLS	7. UNIT AGREEMENT NAME:				
SUNDRY NOTICES AND REPORTS ON WELLS	1				
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 5 652				
	1				
1. oil gas other	G.L. Erwin A. Federal				
	9. WELL NO. 19 19 19 19 19 19 19 19 19 19 19 19 19				
2. NAME OF OPERATOR	4250 9 823				
TEXACO Inc.	10. FIELD OR WILDCAT NAME Justis Tubb Drinkard				
3. ADDRESS OF OPERATOR 88240	Justis Blinebry				
P.O. Box 728 Hobbs, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OR				
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA ညို ချိန် မှ မွန်းမိသို့				
below.)	Sec 35, T-24-S, R-37-E				
AT SURFACE:	12. COUNTY OR PARISH 13 STATE				
AT SURFACE: AT TOP PROD. INTERVAL: 990' FWL & 1980'FSL	Lea 등 사용 등 NM 등 등 등 호				
AT TOTAL DEPTH: Unit Letter 'L'	14. API NO. \$2.55 = 52.56				
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. Selection of the selection o				
REPORT, OR OTHER DATA					
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF KDB, AND WD)				
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3189 (DF) 3255				
TEST WATER SHUT-OFF	े 0 जिस्सा १० जिस्सा १० जिस्सा १० जिस्सा १० जिस्सा				
FRACTURE TREAT	지원 교육 이 그는 그는 그를 가는 그를 가는 그를 가는 것이 되었다.				
SHOOT OR ACIDIZE	len bar 2 yas 3 yas 3 yas 1 bluo 1 bluo 1 bluo 1 drez 1 dr				
REPAIR WELL	(NOTE: Report results of multiple completion or zone				
PULL OR ALTER CASING	change on Form 9-330.) = 1 3 5 3				
MULTIPLE COMPLETE	change on Form 9-330. In the most sage is the change of th				
CHANGE ZONES					
ABANDON*	e and the second secon				
(other) Downhole x	encitairden encitairde lew encitaire ellew encitaire enc				
Commingle					
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	e all pertinent details, and give pertinent dates,				
measured and true vertical depths for all markers and zones pertinent	t to this work.)* 물실원한 표를 모으면				
·	· · · · · · · · · · · · · · · · · · ·				
1 Dinusia na na					
1. Rigged up. Pull pump and rods from 2. Kill Drinkard Zone. Install BOP.	Blinebry, Drill out CIBP @ 5720'				
2. Kill Drinkard Zone. Install BOP.	Test for csg leak. Top of leak				
@ 3570·•	51738 5 KAR				
3. Test Blinebry Zone for leak. Top of	of csg leak @ 3547				
4. Perforate 2-7/8" Blinebry string w	/2-JSPF from 5115 -5924 to				
commingte into prinkard.					
5. Set CIBP @ 5236! Squeeze Blinebry 8	k Drinkard strings looks				
w/125 sx. Class 'C' Cement. WOC. To	ast ose to 1000# Tooted or				
Clean out.	Tested of too too as a second or a second				
6. Drill out CIBP @ 5236'. in Blinebry					
7. Install pumping equipment on 24 hr	$/ \approx 5240^{\circ}$ in prinkard.				
	potential test, well pumped				
bbls oil and 9 bbls wtr producing					
Subsurface Safety Valve: Manu. and Type	Set @ Ft.				
18. I hereby certify that the foregoing is true and correct	그 그 그는 그는 중대 중요하는 과 및 이 작가 및 현				
1 the state of the	ခွေးတို့ကျည်းရှိ ချစ်ပြုသွားရှိသည်။				
SIGNED TITLE ASST. Dist.	Suptr 10-27-78				
(This space for Federal or State office	Ce lise)				
APPROVED BY TITLE	DATE CAN BE SEEN BEST LESS OF THE SEEN BEST				
CONDITIONS OF APPROVAL, IF ANY:					
APPROVED BY TITLE DATE					
1180 m					
*See Instructions on Reverse Side 1978 (177)					
*See Instructions on Reverse Side CIRVEY					
*See Instructions on Reverse Bide To SURVEY 9. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO					
U. S. GEORG.	NEW MIL!				
, ANDO-					

RECEIVE ,

1107 71978

CIL CONCENTRATION COMM.