

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO 30 025 20326	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil / Gas Lease No. B-1583	
7. Lease Name or Unit Agreement Name NEW MEXICO -BZ- STATE NCT-10	
8. Well No. 4	
9. Pool Name or Wildcat JUSTIS BLINEBRY/TUBB-DRINKARD	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator CHEVRON USA INC	
3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705	
4. Well Location Unit Letter <u>M</u> <u>660</u> Feet From The <u>SOUTH</u> Line and <u>989</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>25S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	REQUEST TA STATUS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-02-02: MIRU. UNSEAT PUMP.
12-03-02: TIH ON Y SIDE (BLINEBRY) W/2.35" SHOE ON TBG TO 5222. TIH ON Z SIDE (TUBB-DRINKARD) TO 3850.
12-04-02: TIH W/SHOE TO 5242. SET CIBP @ 5210. MOVED TO 7 STRING SET CIBP @ 5210. TEST CSG & CIBP @ 5210' TO 570 PSI FOR 30 MIN.
BLINEBRY PERFS 5270-5475
12-05-02: TIH W/CIBP & SET @ 5210. CIRC PKR FLUID & TEST CIBP TO 500 PSI FOR 30 MINS. OK. FILL CSG W/PKR FLUID. RIG DOWN.
TUBB DRINKARD PERFS 5270-6083'.

ORIGINAL CHARTS & COPIES OF CHARTS ATTACHED.
DUAL WELLBORE: Y - BLINEBRY AND Z - TUBB-DRINKARD
WELL IS TEMPORARILY ABANDONED.

Period of Temporary
Abandonment Expires 12/17/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 12.12.2002
TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED
CONDITIONS OF APPROVAL, IF ANY:


DATE

DeSoto/Nichols 12-93 ver 1.0




GRAPHIC CONTROLS CORPORATION
CHEVRON/TEXACO
CHART NO. MO. MP-1000
SEC 2, T 255 R37E
2 side
12/5/04
1:00 PM
New Mexico BL STATE
TEST ON CROP @ 5210' IN
TWO-DRAWING STAIRS

6 AM
NOON
6 PM



GRAPHIC CONTROLS CORPORATION
CHEVROLET/TEXACO
CHART NO. MC MP-1000
TEST ON C-130 @ 5210'
4 side
4:00 P.
NEW MEXICO STATE
SEC 2, T255 R37E
12-04-02



6 AM

7

8

9

10



GRAPHIC CONTROLS CORPORATION

CHEVRON/TEXACO
CHART NO. MC MP-1000
SEC 2, T255, R37E

METER

12/5/02

Z side

TAKEN OFF

CHART PUT ON

1:32 PM

1:00 PM

LOCATION NEW MEXICO "B2" STATE
(NCT-10) 2A

REMARKS

TEST ON CIBP @ 5210' IN
TUBB-DRAINAGE STAINING

100

200

300

400

500

600

700

800

900

900

800

700

600

500

400

300

200

100

100

200

300

400

500

600

700

800

100

200

300

400

500

600

700

800

900

3

4

5


6 PM


7

8

9

PEARL E.





CHEVRON/TEXACO
NEW MEXICO '82' STATE (NCT-10) #4
SEC 2, T25S, R37E
PERFS - 5270' - 5475'
TEST ON CIBP IN WEST OF BLINE BAY STAINING @
5210' 12/04/02