

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Project No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032511 (f)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
UNION TEXAS PETROLEUM CORPPRATION

3. ADDRESS OF OPERATOR
1300 Wilco Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Letter "F", 1,650' FNL & 2,310' FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)
3170' DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Stuart

9. WELL NO.
7

10. FIELD AND POOL, OR WILDCAT
Justis (Tubb-Drinkard)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11, T-25-S, R-37-E

12. COUNTY OR PARISH 13. STATE
Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | MULTIPLE COMPLETE <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | ABANDON* <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| (Other) <input type="checkbox"/> | |

SUBSEQUENT REPORT OF:

| | |
|---|--|
| WATER SHUT-OFF <input type="checkbox"/> | REPAIRING WELL <input type="checkbox"/> |
| FRACTURE TREATMENT <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/> |
| (Other) <u>P&A Tubb Drinkard Zone</u> <input checked="" type="checkbox"/> | |

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. July 15, 1974, re-entered well and pulled rods, tubing and pump.
2. July 17, 1974, RU and ran CIBP to 5495' and dumped 15' of cement on top of CIBP.
3. July 19, 1974, ran rods, tubing and pump and placed well on production in Blinebry Zone. Tubb Drinkard Zone now Plugged and Abandoned.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Gas Measurement Analyst

DATE July 28, 1975

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

JUL 30 1975

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side